CITY OF BALTIMORE WET SMOKE AND DYED I	Page 1 of 3			
Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO	Date: 08/27/2008		
Test Type: Smoke	Ground Condition: Dry: X Damp:_ Wet:_	Supervisor: E.R. Crew: 04		
Manhole ID: S19K034MH	Test ID: 1029-571	Notifications Made:X Residents, Fire, 311		

Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses



CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM								Page 2 of 3						
(	Sewershed: Low Level Subsewershed: 44					Company: REI/DRAYCO					Date: 08/27/2008			
Test Type: Smoke				Ground Condition:						Superviros: E.R. Crew: 04				
				Dry: <b>X</b> Damp:_ Wet:_						Notifications Made:X				
Manhole ID: S19K034MH					Test ID: 1029-571						Residents, Fire, 311			
<b>Field Sketch:</b> (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)														
Defect		F	Address		Source			Sector	Drai	nage				
No.	ELIDDO)	M CT	O MOUENDY	СТ	Type					ea				Number OB01-01.jpg
1	FURROW ST. & MCHENRY ST.			51.	12	0	ь	04	18	300	03		1029-571_	ОВ01-01.јрд
											1			
											1			
											1			
											1			
					OB	SED	\/ <b>\</b> T	ION CO	DES					
	Sour	CA T	VNA	1	OB	Loca			DLO		Sector	I	Sev	vority
01 Ma	01	Paved C						Public	01	Severity 01 No Smoke				
			Asphalt					_	Private	_	Trace	<u>-                                      </u>		
				Paved Other					<u> </u>		_	Moderate		
04 Downspout 13 Storm			_									Major		
	ea Drain		Storm Ditch		Sidewal		14	Other	J. 50			۳÷		
	Dwy. Drain 15 Excavation 06 Curb		-	Ė	201				l -					
			Water Line		Yard - F	ront						l -		
			Tele. Pole		Yard - B							l -		
	dg. Interio				Yard - S									

PAGE 3 of 3

## CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

## BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 571 Date: 08/27/2008 Basin: LL - 44 Manhole ID: S19K\_034MH Defect No: OB01 Supervisor: E.R. Crew: 04 Dye Test Recommended: N

Location: FURROW ST & MCHENRY ST

Source Type: 12 Catch Basin Sector: 01 Public

Location: 06 Curb Severity: 03 Moderate Drainage Area: 1800

Comments: STORM DRAIN AT CORNER OF FURROW ST. AND MCHENRY ST. IS SMOKING.

## **SMOKE TEST PHOTOGRAPHS**



Photograph No: OB01-01 Filename: 1029-571\_OB01-01.jpg